intertek

Total Quality. Assured.

ITS Labtest Bangladesh Ltd. Intertek House Bangladesh Ltd. Phoenix Tower (2nd-3rd Floor), 407, Tejgaon I/A, Dhaka-1208, Bangladesh. www.intertek.com

1

Report Number : BA-ENV-2023-08 Date : 09 March, 2023

WORKPLACE ENVIRONMENTAL ASSESSMENT REPORT Illuminance Level Assessment

| Facility Name | : IRIS Fabrics Limited. |
|---------------------------------|--|
| Facility Address | : Zirani Bazar, Kashimpur, Gazipur |
| GPS Coordinate | : Latitude : 23.999265 Longitude: 90.251186 |
| Facility Tel | : +8801817049518 |
| Facility Contact | : Mohammad Ahsan Alim – GM (Admin, HR & compliance) |
| Facility Email | : admin@irisgroupbd.com |
| Description of Equipment | : AS813 Digital Lux Meter |
| Data Collection Date & Time | : 09 March 2023, 10:40 AM-02:55 PM (Running Condition) |
| Conducted By | : Md. Monoarul Islam, & Hasan Tawhid |

Assessment Result :

| Building | Location | Section | Illuminances Level (Lux) |
|-----------------|-----------------------|----------------------|--------------------------|
| | Ground Floor | Embroidery Section | 821 |
| | | Knitting Section | 351 |
| | 1 st Floor | Finishing Section | 781 |
| | | Spot Removing Room | 710 |
| | 2 nd floor | Sewing Section | 832 |
| | 3 rd Floor | Sewing section | 945 |
| Building-1 | 4 th Floor | Finishing section | 802 |
| Building-1 | | Spot removing Room-1 | 618 |
| | | Spot removing Room-2 | 703 |
| | 5 th floor | Sewing section | 765 |
| | 6 th Floor | Cutting section | 825 |
| | 7 th Floor | Sewing Section | 789 |
| | | Finishing Section | 1121 |
| | | Spot removing room | 735 |
| | Ground Floor | Dyeing section | 352 |
| | | Finishing Section | 365 |
| Duilding 2 | | Washing Section | 355 |
| Building-2 | | Chemical sub-store | 205 |
| | 1 st floor | Printing section | 1208 |
| | | Color kitchen room | 445 |
| Utility Section | Ground Floor | Generator room | 355 |

Disclaimer: This report is for the exclusive use of the client of Intertek named in this report and is provided pursuant to an agreement for services between Intertek and Client. No other person may rely on the term of this report. Limiting to the information observed, revealed and provided during the assessment, the report makes no warranties or representation either expressed or implied with respect to the compliance of the environmental as per the requirement of department of environment of Bangladesh. Intertek and conditions of the Client Agreement. Intertek assumes no liability to any party, for any loss, expense or damage occasioned by the use of this information other than to the Client and in accordance with the Client Agreement and these disclaimers.

intertek

Total Quality. Assured.

ITS Labtest Bangladesh Ltd. Intertek House Bangladesh Ltd. Phoenix Tower (2nd-3rd Floor), 407, Tejgaon I/A, Dhaka-1208, Bangladesh. www.intertek.com

Report Number : BA-ENV-2023-08

| Date | : 09 March, 2023 | | |
|-----------------|------------------|-----------------|--------------------------|
| Building | Location | Section | Illuminances Level (Lux) |
| Utility Section | Ground Floor | Boiler room | 354 |
| | | Compressor room | 356 |
| | | ETP | N/A |
| | | WTP | 352 |

Standard Requirement:

| Requirement | Area of activity | Illuminance (lux) |
|---|------------------|------------------------------|
| Bangladesh Labor Law 2006, Section | Workplace | 350 Lux at the height of 1.0 |
| 17, and Bangladesh Labor Rules 2015 | | meter |
| | Matching-up | 450 |
| Pangladash National Duilding Code | Cutting & Sewing | |
| Bangladesh National Building Code 2020, Part 8, Chapter-01, Table 8.1.10 | Light | 300 |
| | Medium | 450 |
| | Dark | 700 |

Comment: The Assessment result of illuminance level of different sections in the facility shows that the illumination level in all the area were found within the acceptable limits.

Report prepared by

M. flem

Md. Monoarul Islam Auditor Supplier Management Business Assurance ITS Labtest Bangladesh Ltd.

Report authorized by



Shoriful Islam Head of Business Assurance Supplier Management Business Assurance ITS Labtest Bangladesh Ltd.

2

Disclaimer: This report is for the exclusive use of the client of Intertek named in this report and is provided pursuant to an agreement for services between Intertek and Client. No other person may rely on the term of this report. Limiting to the information observed, revealed and provided during the assessment, the report makes no warranties or representation either expressed or implied with respect to the compliance of the environmental as per the requirement of department of environment of Bangladesh. Intertek assumes no liability to the authenticity and legality of documents provided. Intertek's responsibility and liability are also limited in accordance to the terms and conditions of the Client Agreement. Intertek assumes no liability to any party, for any loss, expense or damage occasioned by the use of this information other than to the Client and in accordance with the Client Agreement and these disclaimers.